

PIARCO INTERNATIONAL NOTAM OFFICE

AIP SUPPLEMENT

Tele: 1 868 669-4128 1 868 668-8222 ext 2510 FAX: 1 868 669 1716 AFTN: TTPPYNYX Email:aispublications@caa.gov.tt

TRINIDAD & TOBAGO CIVIL AVIATION AUTHORITY, P.O. BOX 2163, NATIONAL MAIL CENTRE, PIARCO REPUBLIC OF TRINIDAD AND TOBAGO

03/24 02 FEB 24

AD

03. A.N.R. ROBINSON INTERNATIONAL AIRPORT (TTCP)

RUNWAY STRIP AT A.N.R. ROBINSON INTERNATIONAL AIRPORT

Effective: 240202 TO PERM


Runway Strip at A.N.R. Robinson International Airport does not meet the Annex 14 Standards and Recommended Practices.

Annex 14 Aerodromes (Vol.1) 9th Edition 2022 part 3.4.3, states a Runway Strip including a precision approach runway shall, wherever practicable, extend laterally to a distance of at least 140 metres, where the code is 3 or 4, on each side of the centre line of the runway and its extended centre line throughout the length of the strip.


Actual Runway Strip dimension is depicted in Attachment A.

Please amend E/CAR AIP GEN 1.7

END



ATTACHMENT A



RWY Distances	RWY Strip (North)		RWY Strip (South)	
	Length	Width	Length	Width
a-b	740m	75m		
b-c	817m	140m		
c-d	760m	72m		
d-e	466m	118m		
e-f	20m	78m		
g-h			40m	37m
h-i			1420m	100m
i-j			436m	45m
j-k			907m	78m

NOTE: DRAWING NOT TO SCALE

