



TRINIDAD AND TOBAGO CIVIL AVIATION AUTHORITY

By Order of
The Director General of Civil Aviation

NOTICE OF FLIGHT PROHIBITION

TO: **ALL OPERATORS OF THE BOEING 737-9 MAX AIRPLANES, CERTIFICATED IN ANY CATEGORY, WITH A MID CABIN DOOR PLUG INSTALLED**
(Operator or Pilot in Command)

OF: **ALL NATIONALITY AND REGISTRATION MARKS**
(Aircraft Nationality and Registration Marks)

Whereas on the 15th day of January 2024 I, CARY PRICE

being duly authorized by the Trinidad and Tobago Civil Aviation Authority, conducted a review of safety data and pursuant to Section 5, 6 and 8 of the Civil Aviation Act No.11 of 2001 and found the said aircraft NOT TO BE in a condition safe for use. You are HEREBY NOTIFIED that the said aircraft is PROHIBITED FROM USE in civil aviation operations within and over Trinidad and Tobago until and unless found by the Director General of Civil Aviation to be in a condition which is safe for use, conditional upon the satisfactory resolution of the under listed safety of flight issues:

1. **In accordance with the United States Federal Aviation Administration (FAA) Emergency Airworthiness Directive – AD # 2024-02-51.**
2. _____
3. _____

Dated this 15th day of January 2024

FOR THE DGCA: Cary D. K. Price